

Page 1 of 2

W.O Number 1899714 /

To CROMWELL

[illegible]

Supervisory Certification

T Schuse

Alfred

TRACK INSPECTION REPORTING FORM

Name T SCHISLER

Date 5/1/15

Page 2 of 2

(Please Print)

Watchman M BLARA

W.O Number 1899714

Inspected From LINTHICUM

To BWI

Item	Exception Chain Marker No.		W.O. Number	Track No.	Rail E/W	Switch No.	Codes		Status S/Y/R	Repair Y/N
	From	To					Comp.	Defect		
1.	45+00 ^{BWI}			1	BOTH		W 301	332	Y	
2.	43+50 ^{BWI}			1	BOTH		W 301	332	Y	
3.										
4.										
5.										
6.										
7.										
8.										
9.										

Item COMMENTS

1	CAMP MEADE X-ING SOUTH, #1 TRACK, BOTH RAILS, 10 TIES IN A ROW PUMPING 3/4" UNDERLOAD, SHOWING SOME LATERAL MOVEMENT, ALSO A ROUGH RIDE
2	CAMP MEADE X-ING SOUTH #1 TRACK, BOTH RAILS, 12 TIES IN A ROW PUMPING 3/4" UNDERLOAD, SHOWING SOME LATERAL MOVEMENT

Were Switch in the area of Inspected Yes X NO

Were all single operating mechanism & connecting rod type switches inside area and operated in each position?

Yes NO X

SPECIAL INSPECTION Yes NO X

Reason for special Inspection ?

Track Inspector Signature

T Schisler

Supervisory Certification

[Signature]

Page 1 of 1

W.O Number 1908707

To Lithuanian Statute

[illegible]

Supervisory Certification [Signature]